

- Products
- Segments
- Support & Services
- Academy
- About
- News
- Products
- Segments
- Government and Public Safety
- Industry and Commerce
- Mining
- Oil & Gas
- Defence and Security
- Humanitarian
- Construction and Manufacturing
- Healthcare
- Hospitality
- Hotel/Casino places its bets on MotoTRBO
- Logistics
- Wildlife Protection
- Ports and Airports
- Support & Services
- Customer Support
- Thuraya specifications access
- Technical Support
- Site survey
- Danimex FTP site
- Support Ticket System
- Repairs
- Danimex Services
- HITS - Humanitarian IT Service
- Videos
- Fundamentals
- OTAP
- Academy
- MOTOTRBO courses
- Webinars
- Hytera courses
- Interested - Reserve a seat
- Terms and conditions
- About
- Company Profile
- Company presentation
- Offices
- Head office Denmark
- Middle East
- South Africa
- Jobs
- References
- CSR - UN Global Compact
- Values
- Code of conduct
- Awards
- Achilles Approval
- ISO 9001
- Credit rating
- Terms and conditions
- General terms and conditions
- Order handling fees
- Warranty and repair
- Copyright notice
- Terms of use
- Privacy policy
- News

+ All News

Corporate news

Product news

Seminars & Events



+ All News

Corporate news

Product news

Seminars & Events

- 2020 DANIMEX ACADEMY TRAINING SCHEDULE**
11/5/2020
- DANIMEX STRENGTHENS ITS PRODUCT PORTFOLIO**
12/6/2019
- 2 AWARDS FOR DANIMEX**
11/12/2019
- RITTAL TRUCK VISIT**
11/5/2019
- AIDEX 2019**
10/17/2019
- BODY WORN CAMERA SOLUTIONS**
8/8/2019
- SATELLITE SERVICE INFORMATION**
7/1/2019
- SMARTPTT CELEBRATES 10TH ANNIVERSARY**
5/31/2019
- NEW FIRMWARE RELEASES FOR IRIDIUM PRODUCTS**
4/25/2019
- MEET US AT PMAWCA IN TOGO**
4/8/2019

MEETING SOLAS REQUIREMENTS WITH MOTOTRBO

11th July 2018





SOLAS Chapter II-2 details fire safety provisions including protection, detection and extinction and Regulation 10.10.4 **requires that a minimum of two two-way portable radiotelephones are carried on board for each fire party**, in order to provide a dedicated means of communication between fire-fighters and a crew member outside the incident area. Depending on the size and type of vessel, it may actually be required to carry more than two devices. From 1 July 2018, all ships will be required to comply with the regulation.

Although Regulation 10.10.4 does not specify the frequency band to be used by the fire-fighter radios, UHF frequencies are most commonly used for on-board communication as they provide better propagation within the metal structures of ships.

With exceptional voice quality, long battery life and ATEX-certified for safety, the **MOTOTRBO DP4000 Ex Series** meets the requirements of SOLAS Chapter II-2 Regulation 10.10.4 for fire-fighter radios carried on board ships.

[See the Solutions Brief to learn more.](#)

[← BACK](#)

[CONTACT](#) [HEADOFFICE](#) [WORLDWIDE OFFICES](#) [QUICK LINKS](#)

Tel.: +45-7342 5600 Danimex Communication **Middle East**
Fax.: +45-7342 5615 Elholm 4, **South Africa**
danimex [@] danimex.comDK-6400 Sønderborg
VAT#/CVR-nr. 29669015 Denmark

[Career opportunities](#)
[Terms and conditions](#)
[Warranty and repair](#)
[CSR and core values](#)
[Sitemap](#)

 **CERTIFIED DISTRIBUTOR**  **CERTIFICATES**

Danimex Communication is an award winning distributor of radio communication solutions and equipment throughout the world.